

ST PAUL Sprinkler Save 12/02/2011

St Paul Fire crews responded to a fire in a basement. Upon arrival crews found that the fire was extinguished by a sprinkler head located in the basement ceiling. The fan located in the basement ceiling overheated and shorting out dropping hot melted plastic on the floor igniting paper and cloths located on the floor. The fuse was in an off position when examined. The sprinkler was then automatically activated with the growth of the fire and then extinguished. Fire crews shut the water off and secured the area. No one was displaced and management was there to assist the homeowners.

SEE PHOTOS BELOW









